

Standard Components - Room Data Sheet

Room Name | Bay - Linen Room Number: BLIN

Last modified 01/03/2016

Briefed Area Remarks

2.00

Occupancy
1-2 intermittently
Hours of Operation

24 Hours

Acoustics
Description / Special
Requirements

A recessed bay to accommodate a clean linen supply or exchange trolley; blankets and pillows may also be stored. The bay may be enclosed with doors or sliding doors, however, an open bay is acceptable if a covered trolley is supplied or the bay is located in non-public access areas.

Room Fabrics

AusHFG code	Description	Material	Finish	Specification	Comments
1000	Floor finish	Vinyl	Standard slip resistant	Seamless, coved	
3000	Wall finish	Paint	Acrylic, washable		
3051	Wall finish	Vinyl	Prefinished	Wall vinyl to 1800 AFFL	To underside of shelf, Default = vinyl
2535	Wall protection			Corner guards to 900 AFFL	
5010	Ceiling - Plasterboard	Plasterboard	Paint, washable	Flush set, suspended	Acoustic tiles acceptable.
9210	Door - 180 deg	Solid Core	Paint	Double leaf	Enclosed bay only. To be decided at project level.
2530	Door protection	Composite	Prefinished PVC	Protection plate to 900 AFFL	
2529	Door protection	Composite	Prefinished PVC	To door frame	
6030	Cornice	Aluminium	Powdercoat	24mm shadow angle	
2000	Skirting	Vinyl	Prefinished	Floor vinyl coved, 150 mmH	

Fittings and Furniture

AusHFG code	Description	Group	Qty	Comments
FF-12340	Trolley - clean linen	3	1	
FF-19800	Shelf - laminate	1		Wall mounted, over trolley, subject to operational requirements.

Fixtures, Equipment and associated Services

Service Requirements

AusHFG code	Description	Comments
S-5000	Airconditioning	
S-6000	General fluorescent	

Services

AusHFG code	Description	Group	Qty	Comments
S-5000	Airconditioning	1	1	
S-6000	General fluorescent	1	1	







Standard Components - Room Data Sheet

Room Name Bay - Linen Room Number: BLIN

AusHFG code	Description	Group	Qty	Comments
S-6200	Light switches	1	1	



